

APPENDIX D: METALLURGICAL EXAMINATION

LN-OJF EC225 Super Puma Accident Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ

QINETIQ/18/00263/1.0

Authors:

Steven Findlay
Steve Harris
Nigel Harrison

26 January 2018

Technical Approval:

Andrew Foreman
Head of Engineering
Research & Consultancy



LN-OJF EC225 Super Puma Accident

Introduction

Examination of Fractured 2nd Stage Planet Gear S/N 10-1292



- Initial Examination
- Fractography of Through Thickness Fracture
- Examination of Outer Race Surface
- X-Ray Tomography
- Microsections Through Subsurface Cracking
- Microsections Through Micro-Pitting
- Fractography of Subsurface Cracks
- Sequential Polishing Through Spalls 1 - 3
- Materials Conformity

Examination of Second Stage Planet Gear Inner Race S/N 10-1292


Examination of Second Stage Planet Gear Carrier

Discussion & Conclusions







Fractured Second Stage Planet Gear Sample FE13961 – As Received



5 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear Sample FE13961 – As Received




SEM examination of the as-received fracture surface shows indications of fatigue (B & C) along with areas of corrosion (A).

6 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear As received



All remaining 2nd stage planet gear fracture surfaces exhibit ductile overload failure

7 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear S/N 10-1292 Through Thickness Fracture



Fractured Second Stage Planet Gear Sample FE13961 – After Cleaning



Cleaning of fracture surface using a combination of acetate replica stripping and inhibited HCl solution with ultrasonic agitation. Crack arrest marks visible on fracture surface after cleaning.

9 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear Sample FE13961 – Summary of Macro Mark Observations




Summary of macro mark observations, solid line – well defined, dashed line – less well defined, see reference [1] for further details. A number of attempts were made to correlate the macro marks with flight data, including engine stop starts, take-off and landings etc. No successful correlations were made.

[1] QinetiQ/16/02442/1.0 – QinetiQ / Airbus Helicopters, Macro Mark Counting, 28 June 2016.

10 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured Second Stage Planet Gear Sample FE13961 – Through Fracture Crack Propagation Direction



11 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear Sample FE13961 – Fatigue Crack Progression Marks (Striations)




Positive identification of fatigue striations observed on a small region of the through thickness fracture surface, towards the centre of the gear.
Insufficient evidence to determine the crack growth rate from striation spacing measurements.

12 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured Second Stage Planet Gear Sample FE13961 – Final Overload Fracture




Fatigue crack propagation accounts for approximately 95% of the through thickness fracture.

13 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear Sample FE13961 Race Surface – After Cleaning




Note: The line placed at 14mm from the upper edge of the planet gear refers to the approximate location of maximum Hertzian stress for a FAG planet gear, as informed by Airbus Helicopters and previously noted in the AAIB report on the G-REDL accident.

15 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Spall 1 As-Received





Mean depth of spall = 282µm, maximum depth 325µm

16 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ





Fractured Second Stage Planet Gear
Sample FE13961 Race Surface – Spall 1 After Cleaning



17 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured Second Stage Planet Gear
Sample FE13961 Race Surface – Spall 1 After Cleaning



18 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Spall 1 After Cleaning



19 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Between Spall 1 and Spall 2



20 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Between Spall 1 and Spall 2




The location of the observed micro-pitting is approximately 15mm from the upper edge of the planet gear – dotted yellow lines.

21 LN-QJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear Sample FE13962 Race Surface – Micro-pitting




A wear track containing micro-pitting is also observed on the upper outer-race surface of the second planet gear fragment (sample FE13962).

22 LN-QJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear Sample FE13962 Race Surface – Micro-pitting




These micro-pits are also located approximately 15mm from the upper edge of the gear and again exhibit undercutting cracks.

23 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Spall 2 As-Received




Mean depth of spall = 317µm, maximum depth 349µm

24 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Spall 2 After Cleaning



25 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ


Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Spall 2 After Cleaning







26 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ

Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Between Spall 2 and Spall 3




small indentations consistent with particle/debris imprints observed between spall 2 and spall 3.




27 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Spall 3 As-Received




Mean depth of spall = 451µm, maximum depth 561µm



28 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Spall 3 After Cleaning



29 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ



Fractured Second Stage Planet Gear Sample FE13961 Race Surface – Spall 4





Mean depth of spall = 1.40mm, maximum depth 1.69mm

30 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ




32 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



34 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ


Fractured 2nd Stage Planet Gear Sample FE14227 – Microsection 16.9mm From Upper Edge



35 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Sample FE13961 – Polished Face 16.0mm From Upper Edge



36 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Sample FE13961 – Polished Face 10.0mm From Upper Edge



37 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Sample FE14228 – Microsection 9.1mm From Upper Edge



38 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Typical Example of Subsurface Crack Propagation – FE14228 (9.1mm)



39 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Typical Example of Subsurface Crack Propagation – FE14228 (9.1mm)



40 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear Typical Example of Subsurface Crack Propagation – FE14228 (9.1mm)




41 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear Sample FE13961 – Microsection 15.0mm From Upper Edge


Microsections showing cracks deviating from the subsurface crack towards the gear tooth roots with a curved path.



42 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear Sample FE14227 – Microsection 16.9mm From Upper Edge




Microsections showing a number of cracks deviating from the subsurface crack and propagating through thickness. A number of cracks also observed propagating towards the tooth root.

43 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Sample FE13961 – Cutting Plan Spall 1 to Spall 3



44 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear
 Sample FE14226 - Transverse Microsection Spall 3



45 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
 QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear
 Sample FE14226 - Transverse Microsection Spall 3



46 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
 QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Sample FE14226 - Longitudinal Microsection Spall 1



Extent of crack from spall 1 on this microsection


Main crack path length = 5.18mm
Main crack length along race surface = 4.19mm




47 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ

Fractured 2nd Stage Planet Gear Sample FE14226 - Longitudinal Microsection Spall 2



Main crack path length = 2.19mm
Main crack length along race surface = 1.80mm




48 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ


QINETIQ

Fractured 2nd Stage Planet Gear Sample FE14226 - Angled Microsection Between Spall 1 and Spall 3


Crack propagation from Spall 1
Main crack path length = 7.15mm
Main crack length along race surface = 6.22mm





Crack propagation from Spall 2 to Spall 3 or a branched crack from Spall 1?
Main crack path length = 1.18mm
Main crack length along race surface = 0.96mm



49 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear Sample FE13962 – Race Surface Micro-Pitting; Transverse Microsection




Sequential grinding & polishing of transverse microsection to reveal micro-pitting and cracking

51 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear Sample FE13962 – Transverse Microsections Through Micro-Pitting



52 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear Sample FE13962 – Race Surface Micro-Pitting; Circumferential Microsection




Sequential grinding & polishing of circumferential microsection to reveal micro-pitting and cracking

Microsections examined at 15.8mm, 15.1mm and 14.9mm from upper surface of gear

53 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Sample FE13962 – Circumferential Microsections Through Micro-Pitting




54 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Sample FE13962 – Circumferential Microsections Through Micro-Pitting



55 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Sample FE13961 – Spall 3 to Main Fracture



57 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Sample FE13961 – Opened Up Fracture



58 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear Sample FE13961 – Fractography Spall 3 to Main Fracture



Micrographs A to C show a decreasing amount of intergranular fracture as the subsurface crack propagates deeper into the material.


One localised region (D) contained features consistent with striations.

Insufficient evidence to determine the crack growth rate from striation spacing measurements.

59 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured 2nd Stage Planet Gear Sample FE14226




60 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear Sample FE14226 – SEM Fractography




Subsurface crack has a predominantly intergranular fracture surface.



61 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



QINETIQ



Fractured Second Stage Planet Gear S/N 10-1292
Sequential Polishing Through Spalls 1 - 3

QINETIQ

Fractured 2nd Stage Planet Gear – Sample FE14226




Objective: To determine the extent (length and depth) of subsurface cracking between spall 1 and spall 2, plus examine the micro-pitting at the origin of spall 1.

63 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear – Sample FE14226 Sequential Polishing



Sequential polishing to determine the extent of subsurface cracking and location of micro-pitting near the origin of spall 1.

Yellow line indicates the location of the slice shown below. A total of 19 slices were examined.




17.6mm from upper surface of gear

64 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured 2nd Stage Planet Gear – Sample FE14226 Sequential Polishing





15.1mm from upper surface of gear

65 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ

Fractured 2nd Stage Planet Gear – Sample FE14226 Sequential Polishing




15.1mm from upper surface of gear

66 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ

Fractured 2nd Stage Planet Gear – Sample FE14226 Sequential Polishing




15.0mm from upper surface of gear

67 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ

Fractured 2nd Stage Planet Gear – Sample FE14226 Sequential Polishing




15.0mm from upper surface of gear

68 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ

Fractured 2nd Stage Planet Gear – Sample FE14226 Sequential Polishing




14.9mm from upper surface of gear

69 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ

Fractured 2nd Stage Planet Gear – Sample FE14226 Sequential Polishing





14.1mm from upper surface of gear

70 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ

Fractured 2nd Stage Planet Gear – Sample FE14226 Sequential Polishing





13.3mm from upper surface of gear

71 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ



Fractured 2nd Stage Planet Gear – Sample FE14226




Approximate location of subsurface crack

72 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ

QINETIQ



Fractured Second Stage Planet Gear Materials Conformity – Residual Stress



Comparison of the measured residual stress profiles from the outer race surface of three planet gears recovered from the LN-OJF accident, including the failed gear M4325, with the profile obtained from a new FAG planet gear outer race.

The residual stress profiles obtained from the LN-OJF gears were as expected.


Residual stress measurements performed by Airbus Helicopters
 [2] FAG-New Manufacturing.xlsx, email from Airbus Helicopters, 16 August 2016.
 [3] LN-OJF_Export Profils Contraincte.xlsx, email from Airbus Helicopters, 15 September 2016.

75 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
 QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Fractured Second Stage Planet Gear Materials Conformity – Surface Hardness and Residual Stress Comparison



| Load (g) | Vickers Hardness | |
|----------|----------------------------------|--------------------------|
| | FAG [M4325; FE13961 Fracture] | SNR [M5362; Heli-one] |
| 10,000 | 725 | 701 |
| 1,000 | 738 | 715 |
| 500 | 771 | 719 |
| 300 | 807 | 734 |
| 200 | 837 | 731 |
| 100 | 854 | 728 |
| 50 | 856 | 743 |



Vickers hardness measurements made on the outer race surface using a decreasing test load shows an apparent increase in surface hardness on the FAG planet gear as the indent sampling depth decreases.

Residual stress profiles measured on new FAG and SNR outer race surfaces shows a greater compressive residual stress at the surface (<50µm) of the FAG gear compared to the SNR.

These results are consistent with the differences in final finishing operations employed by the two suppliers.




Residual stress measurements performed by Airbus Helicopters
 [4] Super Puma Bearing Sizing Stress Comparison, Airbus Helicopters, 332A056057-B, 5 September 2016..

76 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
 QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Fractured Second Stage Planet Gear Comparison of Second Stage Outer Race Hardness Values with G-REDL Data


| Measurement | G-REDL [M1720] | LN-OJF [M4325] | SNR [M5362] |
|--|--|--|---------------------------|
| Depth of carburised layer (Specification 0.85 – 1.70mm) | Most reliable data = 1.3mm (min 0.9mm, max 1.5mm) | Average = 1.25mm (min 1.14mm, max 1.47mm) | 1.28mm |
| Outer race surface hardness (Specification min 660HV10) | 755HV10 | 725HV10 | 701HV10 |
| Core hardness (Specification 340 – 410HB) | 453HV30 (Approx 447HB) | 399HV30 (Approx 394HB) | 414HV30 (Approx 409HB) |



77 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Second Stage Planet Gear Inner Race 10-1292 As-Received



79 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Second Stage Planet Gear Inner Race 10-1292 After Cleaning



Circumferential "wear" bands observed on the inner-race surfaces

80 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ




Second Stage Planet Gear Inner Race 10-1292 After Cleaning – Upper Race Surface



81 LN-QJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Second Stage Planet Gear Inner Race 10-1292 After Cleaning – Upper Race Surface




SEM examination of the micro-pitting on the upper inner-race surface shows features similar to the micro-pitting observed on the outer race.

82 LN-QJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Second Stage Planet Gear Inner Race 10-1292 After Cleaning




Location of micro-pitting on the upper inner-race surface

83 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Second Stage Planet Gear Inner Race 10-1292 After Cleaning – Location of Small Impressions on Race Surfaces




Location of small impressions on race surfaces suspected to be associated with debris particle imprints; mechanical damage and larger indents consistent with roller impacts due to breakup not identified.

84 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Second Stage Planet Gear Inner Race 10-1292 Upper Race Transverse Microsection




Micro-pitting observed on the upper race surface, approximately 16.5mm from upper edge of gear. No indication of micro-pitting on the lower race surface after several iterations of polishing.

85 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ





Second Stage Planet Gear Inner Race 10-1292 Upper Race Circumferential Microsection



86 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ





Second Stage Planet Gear Carrier As-Received – Deformation and Post Damage



Symmetrical deformation of carrier around post of fractured gear



Only one of the planet gear locking tabs remaining attached



Mechanical damage consistent with gear teeth impressions on three posts


89 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Second Stage Planet Gear Carrier As-Received – Post Identification



Hand engraved post numbers identifiable on some posts



4.2 DE LA CT. 63.22.13.810

IDENTIFICATION DES SATELLITES (160) SUR PORTE SATELLITES (140)

REMONTAGE

| REP. | REFERENCE SATELLITE | C L A S S E | N° SERIE | POSITION SATEL. | HEURES FONC. P1 | HEURES DEPUIS REPA. P2 | HEURES LORS DE LA ROTATION | OBSERVATION |
|------|---------------------|-------------|----------|-----------------|-----------------|------------------------|----------------------------|--|
| 1 | 332A52 3335 07 | B | M4334 | 7 | 1080,00 | | | Not recovered |
| 2 | 332A52 3335 09 | B | M4342 | 7 | 1080,00 | | | Not recovered |
| 3 | 332A32 3335 07 | D | M4325 | 7 | 1080,00 | | | Fractured Outer Race |
| 4 | 332A52 3335 07 | B | M4322 | 7 | 1080,00 | | | Not recovered |
| 5 | 332A32 3335 07 | B | M4324 | 7 | 1080,00 | | | Recovered – Deformed Outer Race |
| 6 | 332A52 3335 09 | B | M4350 | 7 | 1080,00 | | | Recovered – Outer & Inner Race, 24 Rollers |
| 7 | 332A32 3335 07 | B | M4314 | 7 | 1080,00 | | | Recovered – Outer Race |
| 8 | 332A32 3335 07 | B | M4377 | 7 | 1080,00 | | | Recovered – Outer Race |

Identification effectuée le: 20/02/15

Non: (PM) = P1 AVANT ROTATION P2 APRES ROTATION DE 180°C

INSPECTION: [Signature]

ATTENTION : UN EXEMPLAIRE DE CETTE CARTE DE TRAVAIL EST A JOINDRE A LA FME DE L'ENSEMBLE.

Airbus Helicopters build record attached to epicyclic module log card after Australian car accident repair

90 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Second Stage Planet Gear Carrier After Plastic Media Cleaning


Mast splines show no major mechanical damage, corrosion of the splines has removed any surface detail.



91 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



Second Stage Planet Gear Carrier Dismantling of Carrier Bearing



Dismantling of carrier plate bearing shows significant corrosion of race surfaces, bearing cage and rollers. Surfaces are too corroded to observe any wear pattern.
All of the rollers exhibit a channel (groove) on their upper surface, this is suspected to be associated with corrosion of the exposed surfaces of the roller between the cage and outer race

92 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ



QINETIQ

100 LN-OJF EC225 Super Puma Accident - Summary of the Metallurgical Examination of the Epicyclic Gearbox Components at QinetiQ
QINETIQ/18/00263/1.0 | January 2018 | © QinetiQ